


快速夹持, 适合小批量工件



三坐标测量机快速组合夹具

INSIZE PLUS

应用



ISY-800113



ISY-010010



ISY-012010



ISY-080010



ISY-080030



ISY-080040



ISY-080060



ISY-030030



ISY-020010



ISY-020020



ISY-020030



ISY-020040



ISY-020050



ISY-050010



ISY-050030



ISY-050090



ISY-050040



ISY-050020



ISY-050050

(mm)

型号	名称	尺寸(长×宽×高)	螺纹孔
ISY-800113	底板	480×700×15	M10

型号	名称	尺寸(长×宽×高)	顶砧面积	顶砧行程
ISY-010010	柔性顶砧	56×46×132	35.3×31	20
ISY-012010	小型柔性顶砧	34×28×94	17.5×23.3	12

型号	名称	直径
ISY-080010	圆锥顶砧	Ø38
ISY-080030	平头顶砧	Ø38
ISY-080040	台阶顶砧	Ø38
ISY-080060	球面顶砧	Ø38

型号	名称	尺寸(长×宽×高)
ISY-030030	底座	178×38×13

(mm)

型号	名称	直径	高度
ISY-020010	连接块	Ø38	25
ISY-020020	连接块	Ø38	30
ISY-020030	连接块	Ø38	35
ISY-020040	连接块	Ø38	40
ISY-020050	连接块	Ø38	45

型号	名称	尺寸(长×宽×高)
ISY-050010	小型双头连接块	88×38×20
ISY-050030	双头连接块	95×38×25

型号	名称	直径	备注
ISY-050090	可调高度连接块	Ø38	调节高度0-20mm
ISY-050040	可调角度连接块	Ø38	可旋转0~±90°
ISY-050020	压砧	Ø38	旋转臂
ISY-050050	侧向限位块	Ø38	3个限位轴(直径5mm)